

CASE STUDY REPORT ON PRIMARY HEALTH CARE CENTRE

LOCATION- HUPARI

DATE-25/08/2019

The health care center located in Hupari is a small center where people visit for general checkups
And it's a center for the medication of small accidents and treating pregnant women.

The health care center is located at the center of the particular area so that the needy people

Can have immediate access to the center. The center has different compartments like a reception, doctors cabin, general wards, operation theatre, delivery room, meeting room, nurse room, examination room, cold storage, store, post-mortem room.

The circulation was inconvenient as the passage was very small. The rooms were small and proper circulation was not maintained. Air circulation was also not proper which increased foul smell and eliminated natural air.

The overall ambience of the center was not maintained as the surroundings were not treated properly.

