

## Case Study Report

**Place of Visit:** Bramha chaitanya Gondavalekar Maharaj Temple, Gondavale.

**Date of Visit:** 24<sup>th</sup> January 2020

**Subject:** Architectural design- IV

**Topic:** Live case study of Yatri niwas in Gondavale.

### Description of Activities:

Following are the points studied during the visit –

The visit was carried out for second year students for studying the different activities and requirements related to the yatri niwas.

The building visited was Brahmachaitanya Gondavalekar Maharaj Temple trust's Yatri Niwas. Here they studied different activities performed in a typical yatri niwas, requirements of residential and administration, different types of room according to the usage and the facilities required to each requirement.

The students were divided into different groups to study the different types of areas like, room, administration area, common facilities, services, landscape, etc.



Figure 1– Entrance and the exterior view of yatri niwas



Figure 2– Students taking measurements and preparing sketches for the same.

**Outcome:**

After visiting the sites, students get acquainted with how public, semi public and private zones are designed and placed according to the requirements. Also they were able to differentiate between administration area, residential area and service area.