

School of Architecture

Site Visit Report

Place of Visit: Gondavale

Date of Visit: 24th January 2020

Subject: Architectural design- IV

Topic: Proposed Site for Yatri Niwas at Gondavale

Description of Activities:

Following are the points studied during the visit –

The visit was carried out to study the different parameters of the proposed site for a Yatri Niwas or Pilgrimage center.

Here they studied the size, shape & width of the accesses, contours present on the site, topography of the land, climatic conditions of the area, etc.



Figure 1- Proposed site

The students were divided into groups and each group was asked to do sketches and take measurements and photographs individually. They were also asked to take the measurement of the access roads. The segregation of space and the details according to the space was also discussed.



Figure 2- Access Road Site

Outcome:

After the visit the students were able to understand the positive and negative spaces created because of activities and circulation. They were able to calculate the area required for the given problem. they also understand the micro-climate local material and construction style.